Maryland Historical Trust State Historic Sites Inventory Form

Magi No.

DOE __yes __no

1. Nam	e (indicate pr	eferred name)		
historic Wil	liam James Dobs	on House		
and/or common				
2. Loca	tion			
street & number	Fairbank Roa	d		not for publication
city, town	Fairbank	vicinity of	congressional district	Fifth
state	MD	county	Talbot	
3. Clas	sification			
Category district building(s) structure site object	Ownership public private both Public Acquisition in process being considered not applicable	Status _X_ occupied unoccupied work in progress Accessible _X_ yes: restricted yes: unrestricted no	Present Use agriculture commercial educational entertainment government industrial military	museum park private residence religious scientific transportation other:
4. Own	er of Prope	rty (give names a	and mailing address	es of <u>all</u> owners)
name Jame	s W. and Norma	J. Chaires		
street & number	507 Ponderosa	Orive	telephone r	10.:
city, town	Bel Air	state	and zip code MD	
5. Loca	ition of Leg	al Descripti	on	
courthouse, regis	stry of deeds, etc. Tal	bot County Clerk	of Court	531
street & number	Talbot County	Courthouse		folio 748
city, town	Easton		state	MD
6. Repr	esentation	in Existing	Historical Sur	veys
title				
date			federal sta	ate county loc
pository for su	rvey records			-
city, town			state	

7. Description			Survey No. T-822	Survey No. T-822
Condition excellentX good fair	deteriorated ruins unexposed	Check one unaltered _X_ altered	Check one original site moved date of move	move

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The William James Dobson house is the third house from the water on the west side of the Fairbank Road on Tilghman Island. Talbot County. Maryland. The two-story, frame house faces west with the principal gable oriented on a north/south axis.

Built for William James Dobson and Annie B. Harrison following their marriage in 1886, this central hall, three bay house has changed little except for the asphalt shingled roof. The exterior is clad in white weatherboards with green pilaster cornerboards. The Dobson house is supported by a brick pier foundation.

The east (main) facade of the Dobson house has a central door with sidelights and a transom, which is flanked on either side by a six-over-six sash window with very narrow moulding. An entry porch shelters the central door consisting of a small gable end roof with turned supports. The four panel door is unusually ornate. There are three six-over-six sash windows on the second floor of the east facade. The green cornice wraps around the house onto the north and south elevations.

Both the north and south elevations have two six-over-six sash windows on the first and second floors.

The second story of the rear elevation has three six-over-six sash windows. The central bay of the first floor, formerly a doorway, has been filled in and has a small six-over-six sash window inserted in its place. There is one six-over-six sash window on the first floor, northern bay. A one room summer kitchen is connected to the rear of the house with an enclosed breezeway at the southwest corner. This kitchen is covered in asbestos shingle siding.

Although there are no chimneys extant. two interior chimneys were original to the house. The house has one built-in closet, and all the original mantles. The interior walls of the summer kitchen are covered in the original wainscoating.

<u>o.</u> 3	ignificance		Survey No.	-
		community planning conservation	law literature military music literature music literatury literature literatu	religion science sculpture social/ humanitarian theater transportation other (specify)
Specific	dates Bu	uilder/Architect		
check:	Applicable Criteria:A _ and/or Applicable Exception:A		EFG	
	Level of Significance:na	tionalstate	<u>X</u> local	
Prepare support	both a summary paragraph of	significance and a	a general statement o	f history and

The William James Dobson house was one of the first houses built on the Edward Fairbanks farm because of Annie Harrison's girlhood friendship with Fairbanks' daughter. Interestingly, although Mr. Dobson was a waterman, he chose a lot which was oriented towards the street rather than one which had more immediate access to the water of Black Walnut Cove.

According to Mr. Dobson's grandson, the lumber for this house was brought to Fairbank on Mr. Dobson's skipjack at the same time that he was transporting lumber for Swan Song and St. John's Methodist Church. The house was built by Edward Harrison, Annie Harrison's brother.

The William James Dobson house is striking in its dignified simplicity. It has been altered little over the years.

10. Geographi	cal Data			
Acreage of nominated property Quadrangle name UTM References do NOT com		ences	Quadra	ngle scale
<u> </u>	rthing	B Zone	Easting	Northing
C		D		
Verbal boundary description		ipping state or c	ounty boundari	es
state	code	county		code
state	code	county		code
11. Form Prep	ared By			
name/title Elizabeth Hug	ghes, archite	ctural hist	orian	
organization Talbot Count	cy Planning O	ffice d	ate 8/90	
street & number Talbot Cou	unty Courthou	se te	elephone 822-	-2030
city or town Easton			tate MD	

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.


The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to: Maryland Historical Trust

Shaw House 21 State Circle

Annapolis, Maryland 21401

(301) 269-2438





Um James Dobson House 7-824

Tilganish I think, Teller Leury, 115

NE elevation

F. Hayles, probe

3 / Ja



JULIAN JAMES DOBEN 18-53 T-822
Tilghman Tistand, Tallbot County, 110.

NORTHEAST ELEVATION

ELITABETH KINGHES, PARTS

E MITANISE IN MINISTER W.